

Shenzhen BCTC Testing Co., Ltd. 1-2/F., Building B, Pengzhou Industrial Park, No.158, Fuyuan 1st Road, Zhancheng, Fuhai Subdistrict, Bao'an District, Shenzhen, Guangdong, China

## **Test Verification of Conformity**

Verification Number: BCTC2404624643-1C

Applicant : PIXREAL Huangshan Co., Ltd.

No.6 Fusi Road, Yao Shun Park, Xiuning Economic Development Zone, Xiuning County, Huangshan City, Anhui Province 245400

Manufacturer : PIXREAL Huangshan Co., Ltd.

No.6 Fusi Road, Yao Shun Park, Xiuning Economic Development Zone, Xiuning County, Huangshan City, Anhui Province 245400

Product : LED Display

Trademark : PIXREAL

Product Type : HIRO 1.5

Additional Type : Please refer to the following page(s).

Report Number : BCTC2404624643-1R

Test Standard : IEC 62321-3-1:2013, IEC 62321-5:2013,

IEC 62321-4:2013+AMD1:2017, IEC 62321-7-1:2015,

IEC 62321-7-2:2017, IEC 62321-6:2015, IEC 62321-8:2017

The EUT described above has been consolidated by us and found in compliance with the council RoHS directive 2011/65/EU and amendment Commission Delegated Directive (EU)2015/863. This verification is only valid for the test results in this report.

RoHS





Tel: 400-788-9558 / 0755-32936262

www.chnbctc.com

This Verification is for the exclusive use of BCTC's client and is provided pursuant to agreement between BCTC and its client. BCTC's responsibility and liability are limited to the terms and conditions of the agreement. The observation and test results referenced in this Verification are relevant only to the sample tested. This Verification by itself does not imply that the material, product, or service is or has ever been under a BCTC certification program.

BCTC

Page 1 of 2

BCTC/TVC-08(19-May-2023)



Shenzhen BCTC Testing Co., Ltd. 1-2/F., Building B, Pengzhou Industrial Park, No.158, Fuyuan 1st Road, Zhancheng, Fuhai Subdistrict, Bao'an District, Shenzhen, Guangdong, China

Verification Number: BCTC2404624643-1C
APPENDIX I
TYPE NAME DESCRIPTION

## Additional Type:

HIRO 1.9, HIRO 2.3, HIRO 2.5, HIRO 2.6, HIRO 2.8, HIRO 2.9, HIRO 3.1, HIRO 3.9, HIRO 4.6, HIRO 5.9, HIRO 1.5Pro, HIRO 1.9Pro, HIRO 2.3Pro, HIRO 2.5Pro, HIRO 2.6Pro, HIRO 2.8Pro, HIRO 2.9Pro, HIRO 3.1Pro, HIRO 3.9Pro, HIRO 4.6Pro, HIRO 5.9Pro, HIRO 1.5R, HIRO 1.9R, HIRO 2.3R, HIRO 2.5R, HIRO 2.6R, HIRO 2.8R, HIRO 2.9R, HIRO 3.1R, HIRO 3.9R, HIRO 4.6R, HIRO 5.9R, AVATAR 1.5, AVATAR 1.9, AVATAR 2.3, AVATAR 2.5, AVATAR 2.6, AVATAR 2.8, AVATAR 2.9, AVATAR 3.1, AVATAR 3.9, AVATAR 4.6, AVATAR 5.9, FIDO 1.5, FIDO 1.9, FIDO 2.3, FIDO 2.5, FIDO 2.6, FIDO 2.8, FIDO 2.9, FIDO 3.1, FIDO 3.9, FIDO 4.6, FIDO 5.9, FIDO 1.5Pro, FIDO 1.9Pro, FIDO 2.3Pro, FIDO 2.5Pro, FIDO 2.6Pro, FIDO 2.8Pro, FIDO 2.9Pro, FIDO 3.1Pro, FIDO 3.9Pro, FIDO 4.6Pro, FIDO 5.9Pro, FIDO 1.5R, FIDO 1.9R, FIDO 2.3R, FIDO 2.5R, FIDO 5.9R

RoHS





Tel: 400-788-9558 / 0755-32936262

www.chnbctc.com

This Verification is for the exclusive use of BCTC's client and is provided pursuant to agreement between BCTC and its client. BCTC's responsibility and liability are limited to the terms and conditions of the agreement. The observation and test results referenced in this Verification are relevant only to the sample tested. This Verification by itself does not imply that the material, product, or service is or has ever been under a BCTC certification program.

**BCTC** 

Page 2 of 2

BCTC/TVC-08(19-May-2023)